

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210

Box 145801

Salt Lake City, Utah 84114-5801

Telephone: (801) 538-5291

Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-03 To (mo./yr.) 1-04
2. DOGM File Number (Mine No.) 5390014
3. Mine Name: Glen Coff Property
4. Mineral(s) Mined (or permitted to mine): Limestone Flag
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
____ 1/4 SE 1/4 NW 1/4, Section 27, Township 20S, Range 1E
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
7. Name of Operator or Company: KSC Rocks Inc
8. Permanent Street Address: 235 N. Main
City, State, Zip: Kanosh Utah 84637
Phone: 435-759-2639 Fax: 435-759-9197
9. Company Representative (or designated operator):
Name: Steven Sorenson
Title: President
Business Address: 235 N. Main
City, State, Zip: Kanosh Utah 84637
Phone: 435-759-2639 Fax: 435-759-9197
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? 120 Tons

RECEIVED

JAN 29 2004

DIV. OF OIL, GAS & MINING

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
About 120 Tons of material was removed
by Track Loader, material was split
into Flagstone
5. How much **additional acreage** was disturbed during the past year? 1/6 of an acre
6. How much acreage was **reclaimed** during the past year? None
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
8. What is the **total disturbed acreage** of entire project at years end? 1/4 of an acre
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.
Layers of Limestone removed for
Flagstone

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3

1. **The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.**
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Title of Operator:

Signature of Operator:

Date:

Steven LaMar Sorenson
President
Steven LaMar Sorenson
Jan 27 - 04